1966 Airstream Tradewind 24' Micro Vintage Campers Loren Schirber 612-501-0358

## **PROJECTED COSTS**



Project Description: Date: 10/12/2023

Modification of tank holding systems. Repair sub floor in bath area. Disconnect frame and secure new sub floor and instal new flooring. Repair seals on original windows. Clean stickiness off wallpaper and prime. Re-assembly of airstream using original wall divider panels and cabinetry. Re-install new bath fiberglass sink, toilet, tub and vanity. Install accessories and lights. Install upholstered cushions. Repair dents in shell. Polish shell and roof.

Purchase cost and transportation to Minneapolis  1 EA \$ 10,343.00  Site Prep and Demolition  Testing Completed: Test gas lines. Test furnace. Test lock on door - Is there a key - Yes Test vindow shades. Will castsing aluminum cover work for new HW heater? Test roof vent. Existing Details Serial #: J0246713. Dry weight. 4,080# 4) Hitch Ball Height. Approximately inches 5) Safety chains. No. 6) Hitch weight. Approx: 418# 7) Hitch ball size 2". 8) Hubeaps. Missing several. No. 9) Spare fire. No. 10) Tire condition. It has four newer tires. Size? Demolition. Vendor: Silver Flamingo. Remove AC from roof. Remove temporary bumper and lights. Remove window shade valances?  Total - Category 02  Framing  Treat exposed rust on interior with POR 15. POR 15, or "paint over rust" material Applying this paint is tricky at best. There are several important considerations including a three step process with degreaser, and a reactant agent, and then the actual paint. The temp and humidity are important. Time between steps is important. Paint is thin as water, and very messy to apply with a brush. Use a garden sprayer. Welding to ro-inforce steel floor framing where rusted. Replace rusted outriggers. Weld new pan under plumbing tanks. Weld supports for new water tanks.  Furnish and install new 5/8" marine grade plywood floor. Detach frame to allow subfloor to slide into channel and be bolted into frame for stability.  Cover plastic wheel wells. Plywood? Necessary?  total - Category 03  Exterior Vents and Doors  Roof and Vents: Refrigerator vent had a leak or the front door did. Install aluminum cover  1 EA \$ 0.00 over refrigerator vent.		Qty.	Unit		Total
total - Category 01 Site Prep and Demolition Testing Completed: Test gas lines. Test furnace. Test Refrigerator. Test lock on door - Is there a key - Yes Test window shades. Will estisting aluminum cover work for new HW heater? Test roof vent. Existing Details Serial #: J0246713. Dry weight. 4,080# 4) Hitch Ball Height. Approximatelyinches 5) Safety chains. No. 6) Hitch weight. Approx: 418# 7) Hitch ball size 2° 8) Hubcaps. Missing several. No. 9) Spare tire. No. 10) Tire condition. It has four newer tires. Size?  Demolition. Vendor: Silver Flamingo. Remove AC from roof. Remove temporary bumper and lights. Remove window shade valances?  total - Category 02  S 392.00  Framing  O EA \$ Test exposed rust on interior with POR 15. POR 15, or "paint over rust" material Applying this paint is tricky at best. There are several important considerations including a three step process with degreaser, and a reactant agent, and then the actual paint. The temp and humidity are important. Time is himportant. Fine is him as water, and very messy to apply with a brush. Use a garden sprayer.  Welding to reinforce steel floor framing where rusted. Replace rusted outriggers. Weld new pan under plumbing tanks. Weld supports for new water tanks.  Furnish and install new 5/8" marine grade plywood floor. Detach frame to allow subfloor to slide into channel and be bolted into frame for stability.  Cover plastic where Wells. Plywood? Necessary?  O EA \$ Test exposed where wells. Plywood? Necessary?  O EA \$ Test exposed rust and lines and lines are for stability.  Cover plastic where Wells. Plywood? Necessary?  O EA \$ Test exposed rust and lines are formed as a substance of the form of the control of the formation of the control of the formation of the control of the contr	Purchase of Camper and Transport				
Testing Completed: Testing Completed: Testing Completed: Test gas lines. Test furnace. Test furnace. Test Refrigerator. Test lock on door - Is there a key - Yes Test window shades. Will existing aluminum cover work for new HW heater? Test roof vent. Existing Details Serial #: J0246713. Dry weight. 4,080# 4) Hitch Ball Height. Existing Details Serial #: J0246713. Dry weight. 4,080# 4) Hitch Ball Height. Approximatelyinches 5) Safety chains. No. 6) Hitch weight. Approx: 418# 7) Hitch ball size 2". 8) Hubcaps. Missing several. No. 9) Spare tire. No. 10) Tire condition. It has four newer tires. Size? Demolition. Vendor: Silver Flamingo. Remove AC from roof. Remove temporary bumper and lights. Remove window shade valances?  Total - Category 02  Treat exposed rust on interior with POR 15. POR 15, or "paint over rust" material Applying this paint is tricky at best. There are several important considerations including a three step process with degreaser, and a reactant agent, and then the actual paint. The temp and humidity are important. Time between steps is important. Paint is thin as water, and very messy to apply with a brush. Use a garden sprayer. Welding to re-inforce steel floor framing where rusted. Replace rusted outriggers. Weld new pan under plumbing tanks. Weld supports for new water tanks.  Furnish and install new 5/8" marine grade plywood floor. Detach frame to allow subfloor to slide into channel and be bolted into frame for stability. Cover plastic wheel wells. Plywood? Necessary?  O EA \$  Texterior Vents and Doors  Roof and Vents: Refrigerator vent had a leak or the front door did. Install aluminum cover  1 EA \$ 0.00 over refrigerator vent.	Purchase cost and transportation to Minneapolis		1 EA	\$	10,343.00
Testing Completed: Test gas lines. Test gas lines. Test furnace. Test Refrigerator. Test lock on door - Is there a key - Yes Test window shades. Will existing aluminum cover work for new HW heater? Test rook ondoor - Is there a key - Yes Test window shades. Will existing aluminum cover work for new HW heater? Test rook vent. Existing Details Serial #: J0246713. Dry weight. 4,080# 4) Hitch Ball Height. Existing Details Serial #: J0246713. Dry weight. 4,080# 4) Hitch Ball Height. Existing Details Serial #: J0246713. Dry weight. 4,080# 4) Hitch Ball Height. Existing Details Serial #: J0246713. Dry weight. 4,080# 4) Hitch Ball Height. Existing Details Serial #: J0246713. Dry weight. 4,080# 4) Hitch Ball Height. Existing Details Serial #: J0246713. Dry weight. 4,080# 4) Hitch Ball Height. Existing Details Serial #: J0246713. Dry weight. 4,080# 4) Hitch Ball Height. Existing Details Serial #: J0246713. Dry weight. 4,080# 4) Hitch Ball Height. Existing Details Serial #: J0246713. Dry weight. 4,080# 4) Hitch Ball Height. Existing Details Serial #: J0246713. Dry weight. 4,080# 4) Hitch Ball Height. Existing Details Serial #: J0246713. Dry weight. 4,080# 4) Hitch Ball Height. Existing Details Serial #: J0246713. Dry weight. 4,080# 4) Hitch Ball Height. Existing Details Serial #: J0246713. Dry weight. 4,080# 4) Hitch Ball Height. Existing Details Serial #: J0246713. Dry weight. 4,080# 4) Hitch Ball Height. Existing Details Serial #: J0246713. Dry weight. 4,080# 4) Hitch Ball Height. Existing Details Serial #: J0246713. Dry weight. 4,080# 4) Hitch Ball Height. Existing Details Serial #: J0246713. Dry weight. 4,080# 4) Hitch Ball Height. Existing Details Serial #: J0246713. Dry weight. 4,080# 4) Hitch Ball Height. Existing Details Serial #: J0246713. Dry weight. 4,080# 4) Hitch Ball Height. Existing Details Serial #: J0246713. Dry weight. 4,080# 4) Hitch Ball Height. Existing Details Serial #: J0246713. Dry weight. 4,080# 4) Hitch Ball Height. Existing Details Serial #: J0246713. Dry weight. 4,080# 4) Hitch Ball Height. Exi	btotal - Category 01			\$	10,343.00
Test gas lines. Test furnace. Test Refrigerator. Test lock on door - Is there a key - Yes Test window shades. Will existing aluminum cover work for new HW heater? Test roof vent. Existing Details Serial #: J0246713. Dry weight. 4,080# 4) Hitch Ball Height. Approximatelyinches 5) Safety chains. No. 6) Hitch weight. Approx: 418# 7) Hitch ball size 2". 8) Hubdapas, Mising several. No. 9) Spare tire. No. 10) Tire condition. It has four newer tires. Size? Demolition. Vendor: Silver Flamingo. Remove AC from roof. Remove temporary bumper and lights. Remove window shade valances?  total - Category 02  Treat exposed rust on interior with POR 15. POR 15, or "paint over rust" material Applying this paint is tricky at best. There are several important considerations including a three step process with degressor, and a reactant agent, and then the actual paint. The temp and humidity are important. Time between steps is important. Paint is thin as water, and very messy to apply with a brush. Use a garden sprayer. Welding to re-inforce stell folor framing where rusted. Replace rusted outriggers. Weld new pan under plumbing tanks. Weld supports for new water tanks.  Furnish and install new 5/8" marine grade plywood floor. Detach frame to allow subfloor to slide into channel and be bolted into frame for stability.  Cover plastic wheel wells. Plywood? Necessary?  0 EA \$ - total - Category 03  Exterior Vents and Doors  Roof and Vents: Refrigerator vent had a leak or the front door did. Install aluminum cover over refrigerator vent.	Site Prep and Demolition				
Test furnace. Test Refrigerator. Test look on door - Is there a key - Yes Test window shades. Will existing aluminum cover work for new HW heater? Test roof vent. Existing Details Serial #: J0246713. Dry weight. 4,080# 4) Hitch Ball Height. Existing Details Serial #: J0246713. Dry weight. 4,080# 4) Hitch Ball Height. Existing Details Serial #: J0246713. Dry weight. 4,080# 4) Hitch Ball Height. Existing Details Serial #: J0246713. Dry weight. 4,080# 4) Hitch Ball Height. Existing Details Serial #: J0246713. Dry weight. 4,080# 4) Hitch Ball Height. Existing Details Serial #: J0246713. Dry weight. 4,080# 4) Hitch Ball Height. Existing Details Serial #: J0246713. Dry weight. 4,080# 4) Hitch Ball Height. Existing Details Serial #: J0246713. Dry weight. 4,080# 4) Hitch Ball Height. Existing Details Serial #: J0246713. Dry weight. 4,080# 4) Hitch Ball Height. Existing Details Serial #: J0246713. Dry weight. 4,080# 4) Hitch Ball Height. Existing Details Serial #: J0246713. Dry weight. 4,080# 4) Hitch Ball Height. Existing Details Serial #: J0246713. Dry weight. 4,080# 4) Hitch Ball Height. Existing Details Serial #: J0246713. Dry weight. 4,080# 4) Hitch Ball Height. Existing Details Serial #: J0246713. Dry weight. 4,080# 4) Hitch Ball Height. Existing Details Serial #: J0246713. Dry weight. 4,080# 4) Hitch Ball Height. Existing Details Serial #: J0246713. Dry weight. 4,080# 4) Hitch Ball Height. Existing Details Serial #: J0246713. Dry weight. 4,080# 4) Hitch Ball Height. Existing Details Serial #: J0246713. Dry weight. 4,080# 4) Hitch Ball Height. Existing Details Serial #: J0246713. Dry weight. 4,080# 4) Hitch Ball Height. Existing Details Serial #: J0246713. Dry weight. 4,080# 4) Hitch Ball Height. Existing Details Serial #: J0246713. Dry weight. 4,080# 4) Hitch Ball Height. Existing Details Serial #: J0246713. Dry weight. 4,080# 4) Hitch Ball Height. Existing Details Serial #: J0246713. Dry weight. 4,080# 4) Hitch Ball Height. Existing Details Height. Existing Details Height. Existing Details Height. Existing Detai			1 EA	\$	-
Test Refrigerator. Test lock on door - Is there a key - Yes Test window shades. Will existing aluminum cover work for new HW heater? Test roof vent. Existing Details Serial #: 10246713. Dry weight. 4,080# 4) Hitch Ball Height. Existing Details Serial #: 10246713. Dry weight. 4,080# 4) Hitch Ball Height. Existing Details Serial #: 10246713. Dry weight. 4,080# 4) Hitch Ball Height. Existing Details Serial #: 10246713. Dry weight. 4,080# 4) Hitch Ball Height. Existing Details Serial #: 10246713. Dry weight. 4,080# 4) Hitch Ball Height. Existing Details Serial #: 10246713. Dry weight. 4,080# 4) Hitch Ball Height. Existing Details Serial #: 10246713. Dry weight. 4,080# 4) Hitch Ball Height. Existing Details Serial #: 10246713. Dry weight. 4,080# 4) Hitch Ball Height. Existing Details Serial #: 10246713. Dry weight. 4,080# 4) Hitch Ball Height. Existing Details Serial #: 10246713. Dry weight. 4,080# 4) Hitch Ball Height. Existing Details Serial #: 10246713. Dry weight. 4,080# 4) Hitch Ball Height. Existing Details Serial #: 10246713. Dry weight. 4,080# 4) Hitch Ball Height. Existing Details Serial #: 10246713. Dry weight. 4,080# 4) Hitch Ball Height. Existing Details Serial #: 10246713. Dry weight. 4,080# 4) Hitch Ball Height. Existing Details Serial #: 10246713. Dry weight. 4,080# 4) Hitch Ball Height. Existing Details Serial #: 10246713. Dry weight. 4,080# 4) Hitch Ball Height. Existing Details Serial #: 10246713. Dry weight. 4,080# 4) Hitch Ball Height. Existing Details Serial #: 10246713. Dry weight. 4,080# 4) Hitch Ball Height. Existing Details Serial #: 10246713. Dry weight. 4,080# 4) Hitch Ball Height. Existing Details Serial #: 10246713. Dry weight. 4,080# 4) Hitch Ball Height. Existing Details Serial #: 10246713. Dry weight. 4,080# 4) Hitch Ball Height. Existing Details Serial #: 10246713. Dry weight. 4,080# 4) Hitch Ball Height. Existing Details Serial #: 10246713. Dry weight. 4,080# 4) Hitch Ball Height. Existing Details Serial #: 10246713. Dry weight. 4,080# 4) Hitch Ball Height. Existing Details Serial #	Test gas lines.				
Test lock on door - Is there a key- Yes Test window shades. Will existing aluminum cover work for new HW heater? Test roof vent. Existing Details Serial #: J0246713. Dry weight. 4,080# 4) Hitch Ball Height. Approximatelyinches 5) Safety chains. No. 6) Hitch weight. Approx: 418# 7) Hitch ball size 2". 8) Hubcaps. Missing several. No. 9) Spare tire. No. 10) Tire condition. It has four newer tires. Size?  Demolition. Vendor: Silver Flamingo. Remove AC from roof. Remove temporary bumper and lights. Remove window shade valances?  total - Category 02  Framing  O EA  Treat exposed rust on interior with POR 15. POR 15, or "paint over rust" material Applying this paint is tricky at best. There are several important considerations including a three step process with degreaser, and a reactant agent, and then the actual paint. The temp and humidity are important. Time between steps is important. Paint is thin as water, and very messy to apply with a bush. Use a garden sprayer. Welding to re-inforce steel floor framing where rusted. Replace rusted outriggers. Weld new pan under plumbing tanks. Weld supports for new water tanks.  Furnish and install new 5/8" marine grade plywood floor. Detach frame to allow subfloor to slide into channel and be bolted into frame for stability.  Cover plastic wheel wells. Plywood? Necessary?  O EA  S 1,964,00  Exterior Vents and Doors  Roof and Vents: Refrigerator vent had a leak or the front door did. Install aluminum cover over refrigerator vent.	Test furnace.				
Test window shades. Will existing aluminum cover work for new HW heater? Test roof vent. Existing Details Serial #: J0246713. Dry weight. 4,080# 4) Hitch Ball Height. Approximatelyinches 5) Safety chains. No. 6) Hitch weight. Approx: 418# 7) Hitch ball size 2". 8) Hubcaps. Missing several. No. 9) Spare tire. No. 10) Tire condition. It has four newer tires. Size?  Demolition. Vendor: Silver Flamingo. Remove AC from roof. Remove temporary bumper and lights. Remove window shade valances?  Total - Category 02  S 392.00  Treat exposed rust on interior with POR 15. POR 15, or "paint over rust" material Applying this paint is tricky at best. There are several important considerations including a three step process with degreaser, and a reactant agent, and then the actual paint. The temp and humidity are important. Time between steps is important. Paint is thin as water, and very messy to apply with a brush. Use a garden sprayer.  Welding to re-inforce steel floor framing where rusted. Replace rusted outriggers. Weld new pan under plumbing tanks. Weld supports for new water tanks.  Furnish and install new 5/8" marine grade plywood floor. Detach frame to allow subfloor to slide into channel and be bolted into frame for stability.  Cover plastic wheel wells. Plywood? Necessary?  O EA \$ - total - Category 03  Exterior Vents and Doors.  Roof and Vents: Refrigerator vent had a leak or the front door did. Install aluminum cover  over refrigerator vent.	Test Refrigerator.				
Will existing aluminum cover work for new HW heater? Test roof vent. Existing Details Serial #: J0246713. Dry weight. 4,080# 4) Hitch Ball Height. Approximately _ inches 5) Safety chains. No. 6) Hitch weight. Approx: 418# 7) Hitch ball size 2". 8) Hubcaps. Missing several. No. 9) Spare tire. No. 10) Tire condition. It has four newer tires. Size?  Demolition. Vendor: Silver Flamingo. Remove AC from roof. Remove temporary bumper and lights. Remove window shade valances?  Total - Category 02  Treat exposed rust on interior with POR 15. POR 15, or "paint over rust" material Applying this paint is tricky at best. There are several important considerations including a three step process with degreaser, and a reactant agent, and then the actual paint. The temp and humidity are important. Time between steps is important. Paint is thin as water, and very messy to apply with a brush. Use a garden sprayer. Welding to re-inforce steel floor framing where rusted. Replace rusted outriggers. Weld new pan under plumbing tanks. Weld supports for new water tanks.  Furnish and install new 5/8" marine grade plywood floor. Detach frame to allow subfloor to slide into channel and be bolted into frame for stability.  Cover plastic wheel wells. Plywood? Necessary?  O EA \$  total - Category 03  Exterior Vents and Doors  Roof and Vents: Refrigerator vent had a leak or the front door did. Install aluminum cover over refrigerator vent.	Test lock on door - Is there a key - Yes				
Test roof vent. Existing Details Serial #: J0246713. Dry weight. 4,080# 4) Hitch Ball Height. Approximatelyinches 5) Safety chains. No. 6) Hitch weight. Approx: 418# 7) Hitch ball size 2". 8) Hubcaps. Missing several. No. 9) Spare tire. No. 10) Tire condition. It has four newer tires. Size?  Demolition. Vendor: Silver Flamingo. Remove AC from roof. Remove temporary bumper and lights. Remove window shade valances?  Total - Category 02  Treat exposed rust on interior with POR 15. POR 15, or "paint over rust" material Applying this paint is tricky at best. There are several important considerations including a three step process with degreaser, and a reactant agent, and then the actual paint. The temp and humidity are important. Time between steps is important. Paint is thin as water, and very messy to apply with a brush. Use a garden sprayer.  Welding to re-inforce steel floor framing where rusted. Replace rusted outriggers. Weld new pan under plumbing tanks. Weld supports for new water tanks.  Furnish and install new 5/8" marine grade plywood floor. Detach frame to allow subfloor to slide into channel and be bolted into frame for stability.  Cover plastic wheel wells. Plywood? Necessary?  O EA \$	Test window shades.				
Existing Details Serial #: J0246713. Dry weight. 4,080#4) Hitch Ball Height.  Approximatelyinches 5) Safety chains. No. 6) Hitch weight. Approx: 418# 7) Hitch ball size 2". 8 Hubcaps. Missing several. No. 9) Spare tire. No. 10) Tire condition. It has four newer tires. Size?  Demolition. Vendor: Silver Flamingo. Remove AC from roof. Remove temporary bumper and lights. Remove window shade valances?  total - Category 02  Framing  O EA \$  Treat exposed rust on interior with POR 15. POR 15, or "paint over rust" material Applying this paint is tricky at best. There are several important considerations including a three step process with degreaser, and a reactant agent, and then the actual paint. The temp and humidity are important. Time between steps is important. Paint is thin as water, and very messy to apply with a brush. Use a garden sprayer.  Welding to re-inforce steel floor framing where rusted. Replace rusted outriggers. Weld new pan under plumbing tanks. Weld supports for new water tanks.  2 EA \$ 828.00  S 982.80  Solven Plastic wheel wells. Plywood? Necessary?  O EA \$  total - Category 03  Roof and Vents: Refrigerator vent had a leak or the front door did. Install aluminum cover over refrigerator vent.	Will existing aluminum cover work for new HW heater?				
Approximatelyinches 5) Safety chains. No. 6) Hitch weight. Approx: 418# 7) Hitch ball size 2". 8) Hubeaps. Missing several. No. 9) Spare tire. No. 10) Tire condition. It has four newer tires. Size?  Demolition. Vendor: Silver Flamingo. Remove AC from roof. Remove temporary bumper and lights. Remove window shade valances?  Item 1 EA \$ 392.00  Total - Category 02 \$ 392.00  Treat exposed rust on interior with POR 15. POR 15, or "paint over rust" material Applying this paint is tricky at best. There are several important considerations including a three step process with degreaser, and a reactant agent, and then the actual paint. The temp and humidity are important. Time between steps is important. Paint is thin as water, and very messy to apply with a brush. Use a garden sprayer.  Welding to re-inforce steel floor framing where rusted. Replace rusted outriggers. Weld new pan under plumbing tanks. Weld supports for new water tanks.  Furnish and install new 5/8" marine grade plywood floor. Detach frame to allow subfloor to slide into channel and be bolted into frame for stability.  Cover plastic wheel wells. Plywood? Necessary?  O EA \$ - total - Category 03  Exterior Vents and Doors  Roof and Vents: Refrigerator vent had a leak or the front door did. Install aluminum cover  over refrigerator vent.					
size 2". 8) Hubcaps. Missing several. No. 9) Spare tire. No. 10) Tire condition. It has four newer tires. Size?  Demolition. Vendor: Silver Flamingo. Remove AC from roof. Remove temporary bumper and lights. Remove window shade valances?  total - Category 02  S 392.06  Framing  O EA \$ -  Treat exposed rust on interior with POR 15. POR 15, or "paint over rust" material Applying this paint is tricky at best. There are several important considerations including a three step process with degreaser, and a reactant agent, and then the actual paint. The temp and humidity are important. Time between steps is important. Paint is thin as water, and very messy to apply with a brush. Use a garden sprayer.  Welding to re-inforce steel floor framing where rusted. Replace rusted outriggers. Weld new pan under plumbing tanks. Weld supports for new water tanks.  Furnish and install new 5/8" marine grade plywood floor. Detach frame to allow subfloor to slide into channel and be bolted into frame for stability.  Cover plastic wheel wells. Plywood? Necessary?  O EA \$ -  total - Category 03  Exterior Vents and Doors  Roof and Vents: Refrigerator vent had a leak or the front door did. Install aluminum cover over refrigerator vent.	,		1 EA	\$	0.00
newer tires. Size?  Demolition. Vendor: Silver Flamingo. Remove AC from roof. Remove temporary bumper and lights. Remove window shade valances?  Itotal - Category 02  S 392.06  Framing  Treat exposed rust on interior with POR 15. POR 15, or "paint over rust" material Applying this paint is tricky at best. There are several important considerations including a three step process with degreaser, and a reactant agent, and then the actual paint. The temp and humidity are important. Time between steps is important. Paint is thin as water, and very messy to apply with a brush. Use a garden sprayer.  Welding to re-inforce steel floor framing where rusted. Replace rusted outriggers. Weld new pan under plumbing tanks. Weld supports for new water tanks.  Furnish and install new 5/8" marine grade plywood floor. Detach frame to allow subfloor to slide into channel and be bolted into frame for stability.  Cover plastic wheel wells. Plywood? Necessary?  O EA \$ - total - Category 03  Exterior Vents and Doors  Roof and Vents: Refrigerator vent had a leak or the front door did. Install aluminum cover  over refrigerator vent.					
Demolition. Vendor: Silver Flamingo. Remove AC from roof. Remove temporary bumper and lights. Remove window shade valances?  **Total - Category 02**  **Treat exposed rust on interior with POR 15. POR 15, or "paint over rust" material Applying this paint is tricky at best. There are several important considerations including a three step process with degreaser, and a reactant agent, and then the actual paint. The temp and humidity are important. Time between steps is important. Paint is thin as water, and very messy to apply with a brush. Use a garden sprayer.  Welding to re-inforce steel floor framing where rusted. Replace rusted outriggers. Weld new pan under plumbing tanks. Weld supports for new water tanks.  Furnish and install new 5/8" marine grade plywood floor. Detach frame to allow subfloor to slide into channel and be bolted into frame for stability.  Cover plastic wheel wells. Plywood? Necessary?  **O EA \$*  **S 1,964.00*  **Exterior Vents and Doors**  Roof and Vents: Refrigerator vent had a leak or the front door did. Install aluminum cover over refrigerator vent.					
and lights. Remove window shade valances?  **Total - Category 02**  **Treat exposed rust on interior with POR 15. POR 15, or "paint over rust" material Applying this paint is tricky at best. There are several important considerations including a three step process with degreaser, and a reactant agent, and then the actual paint. The temp and humidity are important. Time between steps is important. Paint is thin as water, and very messy to apply with a brush. Use a garden sprayer.  Welding to re-inforce steel floor framing where rusted. Replace rusted outriggers. Weld new pan under plumbing tanks. Weld supports for new water tanks.  Furnish and install new 5/8" marine grade plywood floor. Detach frame to allow subfloor to slide into channel and be bolted into frame for stability.  Cover plastic wheel wells. Plywood? Necessary?  **O EA \$	newer tires. Size?				
Treat exposed rust on interior with POR 15. POR 15, or "paint over rust" material Applying this paint is tricky at best. There are several important considerations including a three step process with degreaser, and a reactant agent, and then the actual paint. The temp and humidity are important. Time between steps is important. Paint is thin as water, and very messy to apply with a brush. Use a garden sprayer.  Welding to re-inforce steel floor framing where rusted. Replace rusted outriggers. Weld new pan under plumbing tanks. Weld supports for new water tanks.  Furnish and install new 5/8" marine grade plywood floor. Detach frame to allow subfloor to slide into channel and be bolted into frame for stability.  Cover plastic wheel wells. Plywood? Necessary?  O EA \$  total - Category 03  Exterior Vents and Doors  Roof and Vents: Refrigerator vent had a leak or the front door did. Install aluminum cover over refrigerator vent.	Demolition. Vendor: Silver Flamingo. Remove AC from roof. Remove temporary bumper		1 EA	\$	392.00
Treat exposed rust on interior with POR 15. POR 15, or "paint over rust" material Applying this paint is tricky at best. There are several important considerations including a three step process with degreaser, and a reactant agent, and then the actual paint. The temp and humidity are important. Time between steps is important. Paint is thin as water, and very messy to apply with a brush. Use a garden sprayer.  Welding to re-inforce steel floor framing where rusted. Replace rusted outriggers. Weld new pan under plumbing tanks. Weld supports for new water tanks.  Furnish and install new 5/8" marine grade plywood floor. Detach frame to allow subfloor to slide into channel and be bolted into frame for stability.  Cover plastic wheel wells. Plywood? Necessary?  total - Category 03  Exterior Vents and Doors  Roof and Vents: Refrigerator vent had a leak or the front door did. Install aluminum cover over refrigerator vent.	and lights. Remove window shade valances?				
Treat exposed rust on interior with POR 15. POR 15, or "paint over rust" material Applying this paint is tricky at best. There are several important considerations including a three step process with degreaser, and a reactant agent, and then the actual paint. The temp and humidity are important. Time between steps is important. Paint is thin as water, and very messy to apply with a brush. Use a garden sprayer.  Welding to re-inforce steel floor framing where rusted. Replace rusted outriggers. Weld new pan under plumbing tanks. Weld supports for new water tanks.  Furnish and install new 5/8" marine grade plywood floor. Detach frame to allow subfloor to slide into channel and be bolted into frame for stability.  Cover plastic wheel wells. Plywood? Necessary?  total - Category 03  Exterior Vents and Doors  Roof and Vents: Refrigerator vent had a leak or the front door did. Install aluminum cover over refrigerator vent.				Φ.	202.00
Treat exposed rust on interior with POR 15. POR 15, or "paint over rust" material Applying this paint is tricky at best. There are several important considerations including a three step process with degreaser, and a reactant agent, and then the actual paint. The temp and humidity are important. Time between steps is important. Paint is thin as water, and very messy to apply with a brush. Use a garden sprayer.  Welding to re-inforce steel floor framing where rusted. Replace rusted outriggers. Weld new pan under plumbing tanks. Weld supports for new water tanks.  Furnish and install new 5/8" marine grade plywood floor. Detach frame to allow subfloor to slide into channel and be bolted into frame for stability.  Cover plastic wheel wells. Plywood? Necessary?  O EA \$ 982.80  **Support Support Suppo				\$	392.00
Treat exposed rust on interior with POR 15. POR 15, or "paint over rust" material Applying this paint is tricky at best. There are several important considerations including a three step process with degreaser, and a reactant agent, and then the actual paint. The temp and humidity are important. Time between steps is important. Paint is thin as water, and very messy to apply with a brush. Use a garden sprayer.  Welding to re-inforce steel floor framing where rusted. Replace rusted outriggers. Weld new pan under plumbing tanks. Weld supports for new water tanks.  Furnish and install new 5/8" marine grade plywood floor. Detach frame to allow subfloor to slide into channel and be bolted into frame for stability.  Cover plastic wheel wells. Plywood? Necessary?  O EA \$ - total - Category 03  Exterior Vents and Doors  Roof and Vents: Refrigerator vent had a leak or the front door did. Install aluminum cover over refrigerator vent.	Framing		0.54	•	
this paint is tricky at best. There are several important considerations including a three step process with degreaser, and a reactant agent, and then the actual paint. The temp and humidity are important. Time between steps is important. Paint is thin as water, and very messy to apply with a brush. Use a garden sprayer.  Welding to re-inforce steel floor framing where rusted. Replace rusted outriggers. Weld new pan under plumbing tanks. Weld supports for new water tanks.  Furnish and install new 5/8" marine grade plywood floor. Detach frame to allow subfloor to slide into channel and be bolted into frame for stability.  Cover plastic wheel wells. Plywood? Necessary?  O EA  * 1,964.00  Exterior Vents and Doors  Roof and Vents: Refrigerator vent had a leak or the front door did. Install aluminum cover over refrigerator vent.		s 16 FT Ge (Predicted TI) (Style Presentation Contine) (Critics Cities			
process with degreaser, and a reactant agent, and then the actual paint. The temp and humidity are important. Time between steps is important. Paint is thin as water, and very messy to apply with a brush. Use a garden sprayer.  Welding to re-inforce steel floor framing where rusted. Replace rusted outriggers. Weld new pan under plumbing tanks. Weld supports for new water tanks.  Furnish and install new 5/8" marine grade plywood floor. Detach frame to allow subfloor to slide into channel and be bolted into frame for stability.  Cover plastic wheel wells. Plywood? Necessary?  OEA \$  total - Category 03  Exterior Vents and Doors  Roof and Vents: Refrigerator vent had a leak or the front door did. Install aluminum cover over refrigerator vent.			1 EA	\$	153.20
humidity are important. Time between steps is important. Paint is thin as water, and very messy to apply with a brush. Use a garden sprayer.  Welding to re-inforce steel floor framing where rusted. Replace rusted outriggers. Weld new pan under plumbing tanks. Weld supports for new water tanks.  Furnish and install new 5/8" marine grade plywood floor. Detach frame to allow subfloor to slide into channel and be bolted into frame for stability.  Cover plastic wheel wells. Plywood? Necessary?  total - Category 03  Exterior Vents and Doors  Roof and Vents: Refrigerator vent had a leak or the front door did. Install aluminum cover over refrigerator vent.		Rust			
messy to apply with a brush. Use a garden sprayer.  Welding to re-inforce steel floor framing where rusted. Replace rusted outriggers. Weld new pan under plumbing tanks. Weld supports for new water tanks.  Furnish and install new 5/8" marine grade plywood floor. Detach frame to allow subfloor to slide into channel and be bolted into frame for stability.  Cover plastic wheel wells. Plywood? Necessary?  total - Category 03  Exterior Vents and Doors  Roof and Vents: Refrigerator vent had a leak or the front door did. Install aluminum cover over refrigerator vent.		BUST &			
Welding to re-inforce steel floor framing where rusted. Replace rusted outriggers. Weld new pan under plumbing tanks. Weld supports for new water tanks.  Furnish and install new 5/8" marine grade plywood floor. Detach frame to allow subfloor to slide into channel and be bolted into frame for stability.  Cover plastic wheel wells. Plywood? Necessary?  O EA \$  -total - Category 03  Exterior Vents and Doors  Roof and Vents: Refrigerator vent had a leak or the front door did. Install aluminum cover over refrigerator vent.		The state of the s			
pan under plumbing tanks. Weld supports for new water tanks.  Furnish and install new 5/8" marine grade plywood floor. Detach frame to allow subfloor to slide into channel and be bolted into frame for stability.  Cover plastic wheel wells. Plywood? Necessary?  O EA \$  total - Category 03  Exterior Vents and Doors  Roof and Vents: Refrigerator vent had a leak or the front door did. Install aluminum cover over refrigerator vent.					
Furnish and install new 5/8" marine grade plywood floor. Detach frame to allow subfloor to slide into channel and be bolted into frame for stability.  Cover plastic wheel wells. Plywood? Necessary?  O EA \$  total - Category 03  Exterior Vents and Doors  Roof and Vents: Refrigerator vent had a leak or the front door did. Install aluminum cover over refrigerator vent.			2 EA	\$	828.00
slide into channel and be bolted into frame for stability.  Cover plastic wheel wells. Plywood? Necessary?  total - Category 03  Exterior Vents and Doors  Roof and Vents: Refrigerator vent had a leak or the front door did. Install aluminum cover over refrigerator vent.	pan under plumbing tanks. Weld supports for new water tanks.	AND DESCRIPTION OF THE PERSON NAMED IN COLUMN TWO IS NOT THE PERSON NAMED IN COLUMN TWO IS NAMED			
slide into channel and be bolted into frame for stability.  Cover plastic wheel wells. Plywood? Necessary?  total - Category 03  Exterior Vents and Doors  Roof and Vents: Refrigerator vent had a leak or the front door did. Install aluminum cover over refrigerator vent.					
slide into channel and be bolted into frame for stability.  Cover plastic wheel wells. Plywood? Necessary?  total - Category 03  Exterior Vents and Doors  Roof and Vents: Refrigerator vent had a leak or the front door did. Install aluminum cover over refrigerator vent.	Furnish and install new 5/8" marine grade plywood floor. Detach frame to allow subfloor to		40 SF	\$	982.80
Cover plastic wheel wells. Plywood? Necessary?  total - Category 03  Exterior Vents and Doors  Roof and Vents: Refrigerator vent had a leak or the front door did. Install aluminum cover over refrigerator vent.					
total - Category 03  Exterior Vents and Doors  Roof and Vents: Refrigerator vent had a leak or the front door did. Install aluminum cover over refrigerator vent.  1 EA \$ 0.00 over refrigerator vent.	·		0 EA	•	
Exterior Vents and Doors  Roof and Vents: Refrigerator vent had a leak or the front door did. Install aluminum cover 1 EA \$ 0.00 over refrigerator vent.			U LA	-	1 064 00
Roof and Vents: Refrigerator vent had a leak or the front door did. Install aluminum cover over refrigerator vent.				<b>.</b>	1,904.00
over refrigerator vent.			1 E A	•	0.00
	6		I EA	3	0.00
Re-install exteriior panels that open. 4 EA \$ 98.00	over reingerator vent.				
Re-install exteriior panels that open. 4 EA \$ 98.00					
Re-install exteriior panels that open. 4 EA \$ 98.00					
	Re-install exteriior panels that open.		4 EA	\$	98.00



ıl - Category 04		\$	576.80
erior Frame and Accessories			
Frame and front flange. Strip and treat rust. Paint with POR 15. I also painted the A frame and rear bumper. But this takes a different type of POR paint, designed for UV exposure.	1 EA	\$	512.00
Install new gas regulator with double tank hose.	1 EA	\$	95.30
Install new jack and sbalizing plate on front hitch jack.	1 EA	\$	67.70
Install stabilizing parking supports. Scissor Stabilizer Jack. Includes Szizzor jack crank handle	2 EA	\$	326.50
Replace two rims with new rims that hold hub caps. Dexstar Conventional Steel Wheel - 15" x 6" Rim - 6 on 5-1/2 - Black Powder Coat	2 EA	\$	375.00
Install 4 hub caps. United Pacific Industries A6028P Hub Cap	2 EA	\$	375.00
Welding, Painting Tank Holder. (Has 2 tanks included)	1 EA	\$	648.00
Step - Paint	1 EA	\$	188.00
Keep original license plate light and bracket.	0 EA	\$	0.00
1 - Category 05		\$	2,587.50
erior Shell Repairs and Polishing	1.54	Ф	2 100 00
Sand protective layer. Polish shell and roof	1 EA	\$	3,180.00
1 - Category 06		\$	3,180.00
erior Doors & Awnings Install lock on door and check keys on all side panels.	1 EA	\$	49.00
Front Window Rock Guard - Build frame usig Aluminum U Channel 3/4" with Corner Reinforcement: ½ by 3 inch corner brackets.	1 EA	\$	366.50
Front Window Rock Guard - Cut down	1 EA	\$	30.00

Front Window Rock Guard - Install with Marine City Stainless-Steel Heavy-Duty Telescoping Hatch/Window Adjuster and Stay Support - 13 inches to 23.5 inches.		2 EA	\$	156.00
Front Window Rock Guard - Install stainless steel Hold Down Clamps / Latches.		1 EA	\$	39.60
Front Window Rock Guard - Construct and install using Aluminum Hinge 48": 270 ° Continuous Hinge Without Holes, Aluminum, Door Leaf: 48 in x 2 in W-Each .		1 EA	\$	42.00
Option: New ZipDee Awning - Color: 4695 Tresco Linen. Length: 167 1/4" - Add \$2,000.00		0 EA	\$	0.00
	4695 Traco Linon			
tal - Category 07			\$	683.10
indows & Screens  CAREFULLY Repair original corning curved glass windows. See window next to door for example. Gasket materials included with sale, but 10 years old.		4 EA	\$	683.10 342.00
indows & Screens  CAREFULLY Repair original corning curved glass windows. See window next to door for	60	4 EA 5 EA		
indows & Screens  CAREFULLY Repair original corning curved glass windows. See window next to door for example. Gasket materials included with sale, but 10 years old.  Install screen in frames. Screen color: Silver. Repair two missing screens. Install new window screen clips where broken.	10		\$	342.00
indows & Screens  CAREFULLY Repair original corning curved glass windows. See window next to door for example. Gasket materials included with sale, but 10 years old.  Install screen in frames. Screen color: Silver. Repair two missing screens. Install new window screen clips where broken.	10		\$	342.00 85.25
indows & Screens  CAREFULLY Repair original corning curved glass windows. See window next to door for example. Gasket materials included with sale, but 10 years old.  Install screen in frames. Screen color: Silver. Repair two missing screens. Install new window screen clips where broken.			\$	342.00 85.25
indows & Screens  CAREFULLY Repair original corning curved glass windows. See window next to door for example. Gasket materials included with sale, but 10 years old.  Install screen in frames. Screen color: Silver. Repair two missing screens. Install new window screen clips where broken.  tal - Category 08  umbing		5 EA	\$ \$ \$	342.00 85.25 427.25

Work to be done as follows: 1 EA 4,741.69

1. Replace grey tank with black and grey water tank. 23 Gallon RV Holding Tank 56" x 16 1/4" x 8 1/2" Elkhart Plastics EPI 3366 Qty. 2.

- 2. Run all new PEX waters to bathroom, kitchen, and water heater.
- 3. Install new FRP tub, sink, and toilet surround.
- 4. Install new chrome drain.
- 5. Connect gas line to range and water heater. Install new regulator for dual tanks.
- 6. Set new water heater.
- 7. Install original toilet with new seat.
- 8. Install tub & shower trim.
- 9. Install new lav and faucet. 4" spread Commercial Bar Sink Faucet 4 Inch Center Deck Mount Bar Sink Faucet 2 Hole Brass Constructed & Chrome Polished with 6" Swivel Spout


& Dual Lever Handles

10. Install new kitchen faucet. 4" spread. Commercial Bar Sink Faucet 4 Inch Center Deck Mount Bar Sink Faucet 2 Hole Brass Constructed & Chrome Polished with 8" Swivel Spout & Dual Lever Handles

- 11. Install new toilet seat. Seat Marine or RV White. https://thisoldtoilet.com
- 12. Repair toilet. Install new silinoid valve and trigger switch. U.S. Solid 1/2" Brass Electric Solenoid Valve 12V DC Normally Closed VITON Air Water Oil Fuel

https://a.co/d/37ivNZY. APIELE 16MM Momentary Push Button Switch Mushroom Head Push Button IP65 Waterproof 12V 24V 36 DC 110V 250V AC 5A SPST (16mm, Silver) https://a.co/d/04RMdFn

13. Replace water filter with Ogden Model A and gasket kit. info@alpheusfiltration.com.



Tankless water heater Instant heating abilities

Fuel type: LP (Propane)

6 Gallon Door Dimensions: 15"H x 15"W 10 Gallon Door Dimensions: 15"H x 18 3/4"W

Temperature range: 95°F - 123°F













1 EA 1,223.94

6 507 42

Subtotal - Category 07			Φ	0,307.42
10. Heating, Ventilation, and AC - David. Date: TBD				
Furnish and install new register cover - • Hvac register cover-		1 EA	\$	48.20
Install new rooftop AC with heater. RV Air Conditioner Low Profile 13.5K Quiet AC Unit with Heat Pump, Remote, Non-Ducted. Installed weight: approx. 99 lbs.	400	1 EA	\$	2,191.94

Outdoor unit dimensions: 32 1/2"W x 9"H x 44"D Plenum (ceiling assembly) unit dimensions: 21"W x 2"H x 22 1/2"D Direct replacement for 14" x 14" fan

Use a minimum of 12 gauge wire for installation

Color: white (white interior plenum unit)



Subtotal - Category 10		\$ 2,240.14
11. Electrical		
All wiring is original Test. Specify device color:	1 EA	\$ 0.00
Off White		
Specify switch style		
Pole		

What will run off of 12v will be the interior lights, ceiling fans, water heater and water pump. We can get a small digital gauge installed to know the battery level. When the 12v is dropping or dead, you can plug in the camper and all 12v power would come back on and

Install 12v battery - FVP® VoltEdge® M24-7DC Deep Cycle Marine & RV Battery



310.00 1 EA

lation Install fiberglass insulation in the floor and roof. Spray foam insulation around penetrations		100 SF	\$	316.00
- Category 11	with eighte		\$	2,525.69
	COB LED Strip Lights			
Inztall LED light strips at ceiling above upper cabinets.		1 EA	\$	58.60
Change out outlet boxes to shallow boxes that are flush with fiberglass walls.	~	1 EA	\$	250.00
Furnish and install new light diffuser covers.		5 EA	\$	344.50
Change Light bulbs in fixtures to LED.		1 EA	\$	71.80
Replace gas light on upper cabinet in kitchen dining area with LED fixture.	=	1 EA	\$	80.20
Furnish and install plug in CO2 detector - Kidde® Tamper-Resistant Plug-in Carbon Monoxide Alarm	© Kidde	1 EA	\$	44.70
Furnish and install smoke detector - Kidde® Worry-Free 10-Year Sealed-In Lithium Battery-Powered Ionization Smoke Alarm with Hush™		1 EA	\$	41.10
	Click image to open expanded view			
	to the second se			
Inztall Powermax 110 Volt to 12 Volt DC Power Supply Converter Charger for Rv Pm3-55 (55 Amp)		1 EA	\$	300.80
Install Panel and rough wiring.		1 EA	\$	639.99
fortell Donal and according to		1.54	ø	(20.00
Steel RV Power Inlet				
a. Intin				

al - Category 12		\$	316.00
eling and Walls			
Re-install wall panels and partitions. Use panel with water damage to create new room	1 EA	\$	1,384.00
divider.			
De install hade and other halfs in Comitous	1 EA	e.	055.00
Re-install beds and other built in furniture.	I EA	\$	855.00
1. Catagoria?		ø	2 220 00
ıl - Category 13 wer Surround		\$	2,239.00
ıl - Category 14		\$	0.00
lwork, Doors, Hardware		Ψ	0.00
Replace water damaged board under window next to bed. Solid 3/4" 1x4 White Ash.	8 LF	\$	135.60
Base shoe molding - 2000596024 96" x 0.75" x 0.468" Unfinished Base Shoe	40 I E	\$	194.21
Species: White Ash	0.468"	Ф	174.41
Supplier: Moldings Online	0.749"		
ıl - Category 15	0.011	\$	329.81
inetry, Countertops and Appliances			
Mirrors - Bath fold down mirror is missing the bottom trim piece. Size: 10" x 20" smoothed edges. Needs clips? Mirror inside bedroom closet in good shape.	1 EA	\$	85.00
Re-Install Original Cabinetry. Repair doors that have separated. Glue and clamp. Fill 4" holes from speakers in bottom of upper cabinets.	1 EA	\$	588.00
Remove delaminated veneer from cabinet top under window. Cabinet top is 35 3/8" wide x 20 deep. Laminate new Ash veneer to top of cabinet. Rockler - PSA - Pressure Sensitive Veneer - 24 Inch X 96 Inch. Item #73507	1 EA	\$	187.50
Install new self closing cabinet door hardware.	21 EA	\$	304.50
New cabinet door hardware: Mid-Century Peg Cabinet Knob	3. Novembre de de	\$	90.35

Furnish and install Marmoleum glue down flooring. Forbo Marmoleum Fresco – Sheet 77' wide x 20' lenght. Color: Aqua 3267. Adhesive: 414 Euroflex Lino Plus. If alternative products are to be used consult with the supplier for more information, guidance and warranty. Trowel - Use a 2mm x 6mm V notched or B1 trowel to apply the adhesive.



Subtotal - Category 18		\$ 1,730.00
19. Painting and Decorating		
Stain match - Take panel to get matched with new touch up stain.	1 EA	\$ 60.00
Stain new panels, shelves, veneers, and quarter round to match existing woodwork.	1 EA	\$ 294.00
Paint over wall paper with Eurathane primer.	1 EA	\$ 237.00

Paint - Top half of walls. Color: SW 6477 Tidewater (Paint wheel rims same color)	SW 6477 Tidewater	1 EA	\$	580.0
	Interior / Exterior Location Number: 170-C1			
Paint - Bottom half of walls and and upper cabinet door interiors and exterior textured panels.	SW 8917	1 EA	\$	580.0
Color: SW 8917 Shell White	Shell White Interior / Exterior			
	Location Number: 264-C1			
Spray Paint Rims - Color: SW 6477 Tidewater	SW 6477	4 EA	\$	121.0
	Tidewater Interior / Exterior			
	Interior / Exterior Location Number: 170-C1			
Airstream decals		2 EA	\$	388.0
	AIRSTREAM			
Exterior lights. New tail lights.	à	2 EA	\$	275.2
Exterior rights. New tain rights.		2 LA	Ψ	273.2
Replace all side running lights.		1 EA	\$	185.4
Reflextive markers.	-	2 EA	\$	108.2
al - Category 19			\$	2,828.8
ting, Clean Up and Debris Removal Final Testing of all systems.		1 EA	\$	392.0
Take photos of all systems, switches, and mechanicals, lights, plugs, hookups, and waste ports for oprtations manual.		1 EA	\$	294.0
Disposal and clean-up al - Category 20		1 EA	\$ <b>\$</b>	392.0 1,078.0
Subtotal			\$	43,277.3
orseen Labor - 18%			\$	2,641.2
orseen Materials - 18%			\$	1,660.1

**Grand Total Cost** 

47,578.80