1967 Airstream Overlander 26' Double Micro Vintage Campers Loren Schirber 612-501-0358 **PROJECTED COSTS**



Project Description:

10/9/2023

Repair seals on original windows. Prime and paint walls. Replace flooring with new Marmoleum. Install accessories and lights. Install new fabric covers for upholstered cushions. Repair dents in shell. Polish shell and roof.

	Qty. Unit		Total	Qty.	Un
Purchase of Camper and Transport				1.	.00
Purchase cost and transportation to Minneapolis	1 EA	\$	10,409.60	1.00	F
otal - Category 01		\$	10,409.60		
lite Prep and Demolition		*			
Testing Needed:	1 EA	\$	-	1.00]
Fill water tank. Test pump. Test black tank. Test dump valve.					
Test gas lines. Test furnace. Test Stove.					
Test Refrigerator.					
Test windows.					
Test window shades. Bath shade looks broken.					
Test roof vents. How do they operate?					
Test hood vent.					
Measurements Needed:	1 EA	\$	-	1.00]
Count cabinet doors for hardware and hinge order (Need inset of doors and overlay).					
Measure for mirrors?					
Measure window shades.					
Measure for window curtains.					
Measure size of cushions for new covers.					
Make template for new shower curtain.					
Measure floor and draw out floor plan. Determine total SF of flooring needed.					
Existing Details	1 EA	\$	0.00	1.00	
Serial #	1 EA	φ	0.00	1.00	
Dry weight. 4,180#					
Hitch Ball Height. Approximately inches					
Safety chains.					
Hitch weight. Approx: 450#					
Hitch ball size 2".					
Hubcaps. No.					
Spare tire. No.					
Tire condition. It has four newer tires. 15" drop center.					
-					_
Demolition.	1 EA	\$	350.00	1.00	1
Remove TV antenea.					
Remove 12x12 tile flooring and mastic.					
Remove refrigerator and panel next to it to allow sub floor replacement.					
Remove deep electrical boxes.					
Take cushions out for recovering. Remove covers.					
Remove window curtains. Discard.					
Remove vinyl divider sliding partitions and save for re-install after flooring?					
Remove bed and couch for floor install.					
Remove Boys Toys sign from wall. Discard.					
otal - Category 02		\$	350.00		

Date:

Materials

Materials

Materials

Materials

\$


-

-

Material

Material Supplier

Gas



Furnish and install new 5/8" marine grade plywood floor. Detach frame to allow subfloor to slide into channel and be bolted into frame for stability.		15 SF	\$	286.65	15.00	SF	\$	7.00	8%	Equal or more than 96 SF	\$	- 8%	4.9
Cut holes in roof for new AC units. Weld new plates on.		1 EA	\$	566.00	1.00	EA	\$	200.00	8%			8%	10.
ubtotal - Category 03			\$	852.65				305.00				0.00	14.
4. Exterior Vents and Doors							Materials			Trade Partne	er		Man Hours
Install new roof vent fan. Roof hole is 14" x 14".		1 EA	\$	294.00	1.00	EA	\$	175.00	8%	Make sure to get the SF of the roof SURFACE area, not the SF of the area it's covering. See cover sheet for pitch chart	\$	- 8%	, 3.
ubtotal - Category 04			\$	294.00				175.00				0.00	3.
5. Exterior Frame and Accessories			•				Materials			Trade Partne			Man Hours
Frame and front flange. Strip and treat rust. Paint with POR 15. I also painted the A frame and rear bumper. But this takes a different type of POR paint, designed for UV exposure.		1 EA	\$	388.00	1.00	EA	\$	100.00	8%			- 8%	
Install new gas regulator with double tank hose.		1 EA	\$	81.22	1.00	EA	\$	59.00	8%		\$	- 8%	, 0.5
Install stabilizing parking supports. Scissor Stabilizer Jack	Ž	2 EA	\$	195.50	2.00	EA	\$	50.00	8%		\$	- 8%	<u>,</u> 2.5
Install 4 hub caps. United Pacific Industries A6028P Hub Cap		4 EA	\$	178.00	4.00	EA	\$	25.00	8%		\$	- 8%	, 2.0
Painting Tank Holder. (Has 2 tanks included)		1 EA	\$	334.00	1.00	EA	\$	50.00	Q 0/ ₂		\$	- 80/	8.0
Step - Paint		1 EA	\$	151.00	1.00	EA	\$	75.00			\$	- 80/	2.0
Keep original license plate light and bracket.		0 EA	\$	0.00	0.00	EA	\$	50.00			*	0.00 8%	0.
			¢.						0.70			0,00	
ubtotal - Category 05 6. Exterior Shell Repairs and Polishing			\$	1,327.72			Materials	484.00		Trade Partne		0.00	23. Man Hours
Repair dent/scrape in lower panel		1 EA	\$	140.00	1.00	EA	Materials		8%			8%	4.
Sand protective layer. Polish shell and roof.		1 EA	\$	2,316.00	1.00	EA	\$	200.00			\$	- 8%	60.
ubtotal - Category 06			\$	2,456.00				200.00				0.00	64.
7. Exterior Doors & Awnings			Ψ	2,100100			Materials	200.00		Trade Partne		0.00	Man Hours
Replace weatherstrip on door.		1 EA	\$	152.30	1.00	EA	\$	60.00	8%		\$	- 8%	
Front Window Rock Guard - Clean frame. Install new plexiglass.		1 EA	\$	270.70	1.00	EA	\$ \$	40.00	8%		\$	- 8%	, 6.
Option: New ZipDee Awning - Color: TBD. Length: - Add \$2,000.00		0 EA	\$	0.00	0.00	EA	\$	1,500.00	8%		\$	- 8%	<mark>,</mark> 0.


Subtotal - Category 07			\$	423.00					100.00				0.00		9.0
08. Windows & Screens								Materials			Trade Partne	r			Man Hours
CAREFULLY Repair original corning curved glass windows. See window next to door for example. Gasket materials included with sale, but 10 years old. Install new stainless steel exterior window clips. http://www.vintagetrailerparts.net/viewpart.php?partID=615		7 EA	\$	503.58	7.00		EA		\$ 18.00	8%			\$	8%	10.5
Install screen in frames. Screen color: Silver. Repair two missing screens. Install new window screen clips where broken.	0	7 EA	\$	91.49	7.00) I	EA		\$ 4.00	8%		\$	- 8	8%	1.7
Subtotal - Category 08			\$	595.07					154.00				0.00		12.2
09. Plumbing								Materials			Trade Partne	r			Man Hours
Furnish and install new water inlet.		0 EA	\$	-	0.00		EA		\$ 200.00	8%	If this is selected, DO NOT select the line above	\$	-	8%	0.0
Furnish and install new Water Pressure Regulator Valve, Brass Lead-Free Adjustable Water Pressure Reducer with Gauge and Inlet Screen Filter.		0 EA	\$	-	0.00) I	EA		\$ 28.99	8%		\$	- 8	8%	0.0
Work to be done as follows: 1. All PVC piping to remain. 2. Run all new PEX waters to bathroom, kitchen, and water heater.		1 EA	\$	976.00	1.00) I	EA		\$ 450.00	8%		\$	-	8%	14.0
RV Tankless Water Heater 12 V On Demand Hot Water Heater 42,000 BTU Tankless water heater Instant heating abilities Fuel type: LP (Propane) 6 Gallon Door Dimensions: 15"H x 15"W 10 Gallon Door Dimensions: 15"H x 18 3/4"W		1 EA	\$	782.35	1.00) I	EA		\$ 529.95	8%		\$	-	8%	6.0
Temperature range: 95°F - 123°F Subtotal - Category 09			\$	1,758.35					979.95				0.00		20.0
10. Heating, Ventilation, and AC - David. Date: TBD			*	-,				Materials			Trade Partne	r			Man Hours
Furnish and install new register cover - • Hvac register cover-		1 EA	\$	55.60	1.00) I	EA		\$ 45.00	8%		\$	-	8%	0.2
Remove heater from near front door and re-install after subfloor is replaced.		1 EA	\$	237.00	1.00) I	EA		\$ 25.00	8%		\$	-	8%	6.0
Install new rooftop AC with heater. RV Air Conditioner Low Profile 13.5K Quiet AC Unit with Heat Pump, Remote, Non-Ducted. Installed weight: approx. 99 lbs. Outdoor unit dimensions: 32 1/2"W x 9"H x 44"D Plenum (ceiling assembly) unit dimensions: 21"W x 2"H x 22 1/2"D Direct replacement for 14" x 14" fan Use a minimum of 12 gauge wire for installation Color: white (white interior plenum unit)	REEPHO	I EA	\$	1,899.95	1.00) I	EA		\$ 1,499.95	8%		\$	- (8%	8.0
Subtotal - Category 10			\$	2,192.55					1569.95				0.00		14.2
11. Electrical								Materials			Trade Partne	r			Man Hours
All wiring is original Test. Specify device color: Off White Specify switch style Pole What will run off of 12v will be the interior lights, ceiling fans, water heater and water pump. We can get a small digital gauge installed to know the battery level. When the 12v is dropping or dead, you can plug in the camper and all 12v power would come back on and		1 EA	\$	0.00	1.00		EA		\$0.00	8%		\$	-	8%	0.0
Install 12v battery - FVP® VoltEdge® M24-7DC Deep Cycle Marine & RV Battery		I EA	\$	172.60	1.00		EA		\$ 95.00	8%		\$	-	8%	2.0

Install exterior power receptacle. Stainless steel. Marinco 303SSELBRV 30 Amp Stainless		1 EA	\$	221.00	1.00	EA		\$ 75.00	8%		\$	- 8	<mark>// .</mark>	4.00
Steel RV Power Inlet												Ŭ		
Install Panel and rough wiring. Run new wire for AC and Hot Water heater. Add junctions and move wiring for 12v and 120v. Frame box around panel and cover with FRP. Square D by Schneider Electric Square D - HOM612L100SCP Homeline Load Center with Cover, 100-Amp Fixed Main Lugs, 1-Phase, 6-Space, 12-Circuit, Indoor		1 EA	\$	414.80	1.00	EA		\$ 60.00	8%		\$	- 8'	<mark>%</mark> 1	0.00
Inztall Powermax 110 Volt to 12 Volt DC Power Supply Converter Charger for Rv Pm3-55 (55 Amp)	Image: A start of the star	1 EA	\$	217.52	1.00	EA		\$169.00	8%		\$	- 8	<mark>≫</mark>	1.00
Furnish and install smoke detector - Kidde® Worry-Free 10-Year Sealed-In Lithium Battery Powered Ionization Smoke Alarm with Hush™		1 EA	\$	34.26	1.00	EA		\$22.00	8%		\$	- 8'	<mark>%</mark>	0.30
Furnish and install plug in CO2 detector - Kidde® Tamper-Resistant Plug-in Carbon Monoxide Alarm		1 EA	\$	37.50	1.00	EA		\$25.00	8%		\$	- 81	%	0.30
Change Light bulbs in fixtures to LED.		1 EA	\$	55.52	1.00	EA		\$19.00	8%		\$	- 8'	/o	1.00
Change out outlet boxes to shallow boxes that are flush with fiberglass walls.	<u>nnnnn</u>	1 EA	\$	118.60	1.00	EA		\$ 45.00	8%		\$	- 8	<mark>%</mark>	2.00
Inztall LED light strips at ceiling above upper cabinets.	COBLED Strip Lights	1 EA	\$	78.64	1.00	EA		\$ 8.00	8%		\$	- 8'	<mark>//o</mark>	2.00
Subtotal - Category 11			\$	1,350.44				518.0)			0.00	2	2.60
12. Insulation Subtotal - Category 12			¢	0.00			Materials			Trade Partner		0.00	Man Hou	rs 0.00
Subtotal - Category 12 13. Paneling and Walls			\$	0.00			Materials	0.0)	Trade Partner		0.00	Man Hou	
Subtotal - Category 13			\$	0.00				0.0)			0.00		0.00
14. Shower Surround Subtotal - Category 14			\$	0.00			Materials	0.0)	Material Overag	es	0.00	Man Hou	rs 0.00
15. Millwork, Doors, Hardware							Materials			Trade Partner			Man Hou	
Base shoe molding - 2000596024 96" x 0.75" x 0.468" Unfinished Base Shoe Species: White Ash Supplier: Moldings Online	0.468" 0.749"	48 LF	\$	205.80	48.00	LF		\$ 1.33	25%	REMINDER: Add \$75 PER profile when using Greatlakes	\$	- 2:	5%	2.40
Subtotal - Category 15			\$	205.80				63.84	4			0.00		2.40

Cabinetry, Countertops and Appliances	1.5.1	<i></i>	23 1 0			Materials		0.51	Trade Partne			Man
Mirrors - Bath fold down mirror is missing the bottom trim piece. Size: 10" x 20" smoothed edges. Needs clips? Mirror inside bedroom closet in good shape.	1 EA	\$	67.40	1.00	EA		\$30.00	8%		\$	- 89	6
Pop-up upper cabinet doors. Glue down peeling textured covering. Install trim piece to hold in place.	8 EA	\$	183.20	8.00	EA		\$5.00	8%		\$	- 89	%
Install new self closing cabinet door hardware.	12 EA	\$	145.68	12.00	EA		\$8.00	8%	Count the number of drawers:	\$	0.00 89	10
New cabinet door hardware: Mid-Century Peg Cabinet Knob. Self-closing door hardware.	12 EA	\$	67.66	12.00	EA	\$	1.17	8%		\$	- 89	%
Counter Tops: Keep existing laminate tops.	1 EA	\$	-		00 EA			8%		\$	- 89	<u>%</u>
<u>APPLIANCES: Install fridge, Take out to install new flooring.</u> Supplier:	1 EA	\$	70.00	1.00	EA	\$	-	8%		\$	- 89	/ 0
otal - Category 16		\$	533.94			Materials	180.04	1			0.00	
pecialties - Install new roller shades on windows. Color: Sizes Needed Kitchen Sink: Width x Length Bath: Width x Length https://cityshadecompany.com/products/roller-shades-old	2 EA	\$	164.60	2.00	EA		60.00	8%	Trade Partne		- 89	Man %
Install shelf liners in cabinets and drawers. Brend: Modmate Shelf Liner,Grip Kitchen Drawer Liners, 12 Inch x 50 FT Design Cabinet Liners for Shelves, Easy to Install Non Adhesive Bathroom Drawer Liner,Non Slip Pantry Shelf Liners Color: (Gold and White)	0 EA	\$	-	0.00	EA	\$	80.00	8%		\$	- 89	1
Re-install vinyl divider sliding partition.	2 EA	\$	140.00	2.00	EA			8%		\$	- 89	%
Upholstery - Bench and Bed Seat Cushion Covers. Front pull out couch cushions, arm rests, and pillows. Pull out bed cushions	1 EA	\$	1,331.00	1.00	EA		\$1,200.00	8%		\$	- 89	%
Install new shower curtain.	1 EA	\$	89.00	1.00	EA		\$0.00	8%		\$ 5	0.00 89	<mark>%</mark>
 Window Coverings – All curtains are lined, pleated and have new curtain carriers. Fabric:TBD i. Front window by hitch. ii. Street side living. iii. Door side living. iv. Kitchen sink Roller shade no curtain. <lu>v. Street side bedroom.</lu> 	1 EA	\$	610.00	1.00	EA		\$0.00	8%		\$ 50	0.00 89	70

otal - Category 17			\$ 2,334.60				1320.00				550.00		9.0
Flooring Floor prep. Smoothing, leveling, etc.		5 EA	\$ 310.00	5.00	EA	Materials	25.00	Q 0/.	Trade Partner	r S	-	00/	Man Hours
 Furnish and install Marmoleum glue down flooring. Forbo Marmoleum tiles 9.8" x 9.8" Pattern: 13. Colors: Cloudy Sand, Stardust, Laguna, Satellite. Light steps Cloudy Sand and Startdust. Dark Steps: Laguna and Satellite. 	2.2	1 EA	\$ 874.82	1.00	EA	137.69 per carton. \$	550.76			\$		8%	8.
Adhesive: 414 Euroflex Lino Plus. If alternative products are to be used consult with the supplier for more information, guidance and warranty. Trowel - Use 2 and 1 and 2 and	Foorplan 13: Tiles 50x25 cm. Colors: 13722, 13711, 1370781												
otal - Category 18	Hoorpian 13: Hies 50x25 cm. Colors: t3/22, t3/11, t3/07& t	3568	\$ 1,184.82				675.76	3			0.00		13.
Painting and Decorating						Materials			Trade Partner	r			Man Hours
Masking and prep for painting to protect surfaces.		1 EA	\$ 312.40	1.00	EA	\$	30.00			\$	-	8%	8.
Stain match - Take panel to get matched with new touch up stain.		1 EA	\$ 62.50	1.00	EA	\$	50.00	25%		\$	-	25%	0.0
Stain new panels, shelves, veneers, and quarter round to match existing woodwork.		1 EA	\$ 315.00	1.00	EA		\$0.00	25%		\$	- :	25%	6.
Refinish cabinets and panels that have worn. Lightly sand. Stain where needed. Seal with clear water based polyurethane.		1 EA	\$ 393.20	1.00	EA	\$	40.00	8%		\$	-	8%	10.0
Paint over wall paper with Eurathane primer.		1 EA	\$ 221.00	1.00	EA		\$75.00	8%	total SF from drywall ceiling AND skimming	\$	-	8%	4.(
Paint - Walls. Color: White Sand SW 9582	Consent Consequence Edition ① Expert Pole Test sets White Stand Pall Datasets ~ Test this coder in a: Color sample Datasets Polec.	1 EA	\$ 431.00	1.00	EA		\$75.00	8%	total SF from drywall WALLS section in green cell to the left	\$	-	8%	10.
Paint - Upper cabinet door interiors and exterior textured panels. Color: SW 6773 Rapture Blue	sw 6773 Rapture Blue Full ottails ~ Gethis color in a: Calc Sample Paint Sample Interior Paint	1 EA	\$ 81.00	1.00	EA	\$	75.00	8%	Standard bathroom line item. MODIFY TO FIT PROJECT! Stain or paint? Is there a window	\$	-	8%	0.
Spray Paint Rims - Color: SW 1668 Pineapple Cream	The set of	4 EA	\$ 120.80	4.00	EA		\$15.00	8%	to paint or not, etc. total SF from drywall WALLS section in green cell to the left	\$	-	8%	1.
Airstream decals	AIRSTREAM	2 EA	\$ 312.80	2.00	EA	<u>\$</u>	80.00	8%		\$	-	8%	4.
Exterior lights. New tail lights.		2 EA	\$ 211.28	2.00	EA	\$	33.00	8%		\$	-	8%	4.
Replace all side running lights.		1 EA	\$ 139.56	1.00	EA	\$	32.00	8%		\$	-	8%	3.

Reflextive markers.	2 EA	\$ 79.18
Subtotal - Category 19		\$ 2,679.72
20. Testing, Clean Up and Debris Removal Final Testing of all systems.	1 EA	\$ 280.00
Take photos of all systems, switches, and mechanicals, lights, plugs, hookups, and waste ports for oprtations manual.	1 EA	\$ 210.00
Disposal and clean-up	1 EA	\$ 280.00
Subtotal - Category 20		\$ 770.00
Project Subtotal		\$ 29,718.26
1. Unforseen Labor - 18%		\$ 1,816.29
22. Unforseen Materials - 18%		\$ 1,353.07
Grand Total Cost		\$ 32,887.61



8%		\$	-	8%	2.00
			0.00		52.60
	Trade Partne	r			Man Hours
8%		\$	-	8%	8.00
8%		\$	-	8%	6.00
8%	4 for bath, 8 for kitchen,	\$	-	8%	8.00
			0.00		8.00
	Trade Partne	r			Man Hours

Large Project Modifier
1
Distance Modifier
1.00